

FIG. 1

0954963 051401




FIG. 2

095496 "E964960"




FIG. 3




FIG. 4

FIG. 5

09254963.051401
T04T50" E9645260




FIG. 6




FIG. 7

09054963 054401
104750 10645850

92

THE CHANNELS OF
THE NEW USER
SERVICE ARE
ORDERED BY THEIR
DESIRED RECEPTION
QUALITY, SUCH AS
A SIR

FIG. 7A

94

DETERMINE
DOWNLINK
PHYSICAL
CHANNELS FOR A
REASSIGNMENT
USING A QUALITY
ESTIMATE

FIG. 7B

96

DETERMINE UPLINK
PHYSICAL
CHANNELS FOR
REASSIGNMENT
USING A
FRAGMENTATION
GAUGE

FIG. 7C

98

THE TIME SLOTS OF THE "BAD"
CCTVCH ARE ORDERED FROM
HIGH INTERFERENCE TO LOW
INTERFERENCE

100

IN THE TIME SLOT ORDER,
ATTEMPT TO REASSIGN PHYSICAL
CHANNELS IN DECREASING
ORDER OF REQUIRED SIR

FIG. 7D